


Chittenden Solid Waste District Bedrock Well Evaluation Bedrock Geology



Legend

- Street address
- Parcel boundaries from 2007
- Assumed well locations, from road inspection by C. Heindel and W. Shellito (H&N, April 2008):**
 - Seen from road, well tag # not confirmed
 - Not seen from road
 - HN added well, seen from road, but not shown on state database map
 - HN moved state database well location, seen from road, well tag # not confirmed
 - Bedrock monitoring well, CSWD approximate location
 - Well tag or completion report number
- Geological Units:**
 - Cdu - Dunham Fm
 - Cc - Cheshire Fm
 - CZp - Pinnacle Fm
 - Unk
- Geological Features:**
 - Hinesburg/Lake Iroquois thrust fault (teeth on upper plate)
- Heindel and Noyes:**
 - Hydrogeology
 - Ecology
 - Environmental Engineering

July 15, 2008
 Map produced by: M. Shellito
 Z:\Projects\CSWD\IMXD\Bedrock_Well_Evaluation_BdrcGeol_11x17.mxd